

anship 14 S, R 35 E

Between 31 - 32 on North Boundary. Retracement of T 14 S, R 35 E

Orig. 8" pine N 45° E 14 lks. now 12", living and scribe visible.

Orig. 18" tamarack N 60° E 50 lks. is actually N 60° W. Now snag, scribe visible.

Orig. Stone 20 x 10 x 8 in mound per notes.

9/10 Orig. stone Ok. We built stone mound around same.  
16/15

Orig. 28" red fir Now 32" N 37° E 44 lks. OK. I put alum location tag on NE BT.

Orig. 20" Red Fir S 49 E 44 lks. Now snag 3 ft. high. Scribe visible.  
I scribed new 10" Fir S 26 E 28.8 ft. "S15" "CS".

Orig. Y. Pine 40" S 35° W 117 lks. Now snag with scribe visible.  
I scribed new 10" pine S 30° W 13.3 ft. "S 16" "CS".

Orig. 10" W. Fir N 39 W 36 lks. now 12" in good condition.

This corner is about 100 ft. east of high open knoll on main ridge top N.N.W.  
I painted arrow on big rock on knoll pointing to Section Corner.

1/4 Corner 9/16 Stone in mound Ok.  
Orig. 30" Y Pine S 34 E 87 lks. Now rotted Windfall.

Orig. 28" Y. Pine N 8 W 47 lks. Now 36" in good condition. Replaced alum. tag on BT

I scribed 36" Y. Pine S 20 1/2° E 11.0 ft. "1/4 S" "CS".

1/4 8/9 Stone OK

One Bearing Tree in good condition and one poor. I scribed 20" fir Brg. blank  
36.2 ft. "1/4 S" "BT" facing corner.

5/4 Original stone OK  
8/9

Orig. 26" Y. Pine N 64° E 94 lks. now windfall with good scribe.

The other three Y Pine BTs are in good condtion. The NW one bearing N 35° W  
rather than N 45° W as recorded. This corner is just east of 12 ft. jog in  
E-W fence line.

8/9 Stone OK 18 x 12 x 8  
17/16

Orig. 12" W Fir N 40 1/2° E 49 lks. OK now 18"

Orig. 30" Tam. S 26 1/2° E 93 lks. blank.

Orig. 22 Y. Pine S 50° W 20 lks. Now snag.

Orig. 28" Y. Pine N 50 W 12 lks. OK now 32".  
Tag on NW BT.

1/4 corner 4/9. The original stone and both BT's are gone as this falls in "Y" of  
newly constructed US FS roads. US FS marked two reference trees before construction,  
however. I reset corner by intersecting their distances from their reference trees.

Drove 5/8" reinforcing iron in stone mound and scribed two new BT's as follows:  
24" Tam. Snag S 83° E 152.6 ft. "1/4 S" "BT" } Orig. US FS  
36" Tam. S 62 W 146.6 ft. } reference trees

26" Pine N 80 W 119.9 ft. "1/4 S" "BT. Put alum. tag painted red on NW BT.

1/4 corner 9/10 Stone OK

Orig. 10" W Fir S 15° E 31 lks. Now 18"

Orig. 26" W Fir S 24° W 29 lks. Now 32".

5/4. I did not have the notes with me, but found a marked rock and original scribe on  
rotted 14" fir S 35 E about 16 ft. distance and found scribed 8" Fir snag S 51° W  
about 13 ft. I scribed and witnessed two new trees as follows:

16" Fir N 84° W 12.8 ft. "S5" "CS"

6" Fir S 10° E 9.7 ft. "S 4" "CS"

I cut 24" "X" in big fir on west edge of road up Deardorff Creek at point about 600 ft.  
east of this corner. Also put location tag on same big fir.

1/4 Corner 5/4. I did not have copies of original notes, but found stone with "1/4 on West."

12" Tam. N 31° W about 20 ft. with scribe. and 14" tam. windfall with scribe  
S 19 E 11.2 ft. I scribed new 16" Fir N 36 E 15.7 ft. "1/4 S" "CS".

*H. E. Taylor*  
1957

*See Remex  
filed 9/3/88*  
*See Remex  
filed 9/3/88*