



Scale 1"=100'

**BASIS OF BEARINGS**

Survey No. 1163

**LEGEND**

- Found 1" iron pipe with attached brass cap monumented by Carl Stout, see remonumentation sheet filed in the county surveyor's office.
- Found 5/8" iron pin, See Survey No. 304.
- Found 5/8" iron pin with attached aluminum cap, See Survey No. 1163.
- Set 5/8"x30" iron pin with attached red plastic cap marked CORNERSTONE SURVEYING, INC.
- ( ) Record bearing and distance.
- x—x Fence line

**NARRATIVE**

This survey was performed at the request of Mike and Kathy Buckner. The purpose of this survey was to establish and mark a proposed boundary adjustment line.

I searched the available records pertaining to this survey. Survey No. 1163 established the right of way for County Road No. 76. I found and accepted the monuments on the right of way as shown. I found and accepted the monument at the C1/4 corner of Section 29 which was established in Survey No. 304. The monument at the N1/4 corner of Section 29 that was set in Survey No. 304 has been destroyed. The current corner monument was set by Carl Stout, PLS No. 2632, which I accept. The proposed boundary line is positioned at the location approved by both land owners. I set the new monuments in accordance with the evidence I found.

RECEIVED AND FILED

MAR 14, 2006  
OFFICE OF COUNTY SURVEYOR  
Attest: [Signature]

REGISTERED PROFESSIONAL LAND SURVEYOR

[Signature]  
OREGON  
SEPT 19, 1995  
JACK L. WATSON  
2734  
Renewal Date 6/30/2006



**CORNERSTONE SURVEYING, Inc.**  
233 S. Canyon Blvd., John Day, Oregon 97845  
(541) 575-1813

MAP OF SURVEY PROPOSED BOUNDARY LINE ADJUSTMENT SITUATED IN THE NW1/4 OF SECTION 29 T13S, R31E, W.M.	
GRANT COUNTY, OREGON	
SURVEYED FOR: <b>Michael and Kathy Buckner</b>	
SURVEYED BY : Jack Watson	Date: 3/21/2006
DRAWN BY : Jack Watson	