



Found 3/4" iron pin disturbed during fence construction. Found pin East 0.16"

(S 55° 08' 36" W)
S 55° 08' 36" W
1381.13
(1395.3)

To the monument at the C.C. between sections 1 & 2, T14S, R 31E, W.M.

JIM THOMASON

CATHOLIC CEMETERY

Found fence corner post set in concrete.

S 89° 49' 14" E
13.09
(N 89° 18' E)

REGISTERED PROFESSIONAL LAND SURVEYOR

Robert D. Baggett

OREGON
JULY 12, 1963
ROBERT D. BAGETT
598

NARRATIVE: This survey was performed at the request of George Benson, Don Boyer and Charlie Lewis acting on behalf of the Mid County Cemetery Maintenance District. The purpose of the survey was to delineate the triangular shaped tract of land so that the Cemetery District could acquire it from Jim Thomason. A search was made of the available records pertaining to this survey. Field measurements were made to locate existing monuments. New monuments were set in accordance with the evidence found and at locations pointed out to me by the three representatives of the Cemetery District. I found no unusual conditions with this survey.



BASIS OF BEARINGS
RECORD MAP OF SURVEY NO. 201

LEGEND

- Found monument as shown, see map of survey no. 201
- Set 5/8" x 30" iron pin with attached yellow plastic cap marked B-G-A SURVEY MARKER
- x — x Fence line
- () Record bearing and distance

REFERENCES

Record Map of Survey No. 201
Deed Records Book 103 Page 482
104 207
49 448-449
102 623

RECEIVED AND FILED

AUG 22 1985

OFFICE OF COUNTY SURVEYOR

Robert D. Baggett
Attest: *Carol King, Co. Clk.*

 BAGETT - GRIFFITH & ASSOCIATES
John Day, Oregon

MAP OF A SURVEY
SITUATED IN THE SW 1/4 SE 1/4 SECTION 35, T13S, R31E, W.M.

GRANT COUNTY, OREGON

SURVEYED FOR	MID-COUNTY CEMETERY MAINTENANCE DIST.	
SURVEYED BY	R.D.B. & J.L.W.	7/26/85
Scale: 1" = 50'	Drawn by: J.L.W.	7/26/85

RECORD MAP OF SURVEY NO. 880