

Rock 2' x 2' x 1/2' marked B.O. bears S33°00'E 17.8 feet  
 (B.L.M. S33°E 17.8 feet)  
 Pine snag 26" dia. bears record S30°E 2.6 feet  
 Pine stump 18" dia. bears S21°45'W 23.5 feet  
 (unknown origin B.L.M. S22°W 23.4 feet)  
 D. Fir 10" dia. bears record S49°W 4.9 feet  
 Roothole with Pine stump alongside 14" dia. bears  
 S68°24'W 41.0 feet (record S68°W 39.6 feet)  
 Roothole with Pine 14" dia. alongside bears N73°32'W  
 41.0 feet (record N63°W 41.6 feet)  
 D. Fir 10" dia. bears N28°59'W 9.8 feet  
 (B.L.M. N30°W 9.6 feet)  
 Pine snag 29" dia. bears N27°28'W 20.0 feet  
 (unknown origin B.L.M. N28°W 19.8 feet)

1/4 corner 3|2 : Set a 2" x 30" flanged G.I. pipe with  
 a 2-1/2" brass cap exposed 6" from which I mark the  
 following trees as required, taking measurements to  
 the center of the tree at the lower blaze in which  
 I place a brass washer marked LS 1679:

D. Fir 9" dia. bears S45°06'E 61.0 feet  
 P. Pine 8" dia. bears S26°52'W 40.1 feet

Section corner 3|2 : Found a standard B.L.M. pipe and  
 10|11  
 brass cap dated 1967 and buried 8" in a Jeep road  
 (This monument is not of record) from which:

Dead and down Tamarack 14" dia. bears N51°54'E 44.3 feet  
 (record N52°E 44.2 feet)  
 L. P. Pine snag 12" dia. bears N58°37'E 48.9 feet  
 (B.L.M. Noble Fir 11" dia. N61°E 48.8 feet)  
 Fir 10" dia. bears S49°46'E 48.5 feet  
 (B.L.M. Black Pine 7" dia. S46-1/2°E 47.5 feet)  
 L. P. Pine snag 9" dia. bears S45°41'W 63.3 feet  
 (B.L.M. D. Fir 7-1/2" dia. S46°W 62.7 feet)  
 Tamarack stump bears S54°24'W 16.2 feet  
 (record S52°W 15.2 feet)  
 Fir 18" dia. bears N43°46'W 37.8 feet  
 (B.L.M. Black Pine 14" dia. N42°W 38.3 feet)  
 I mark a D. Fir 17" dia. bears N67°42'E 31.2 feet  
 I mark a W. Fir 10" dia. bears S43°41'W 69.8 feet

1/4 corner 2 : Found a standard B.L.M. pipe and brass  
 11  
 cap dated 1968 and exposed 10" in a mound of stone  
 (This monument is not of record) from which:

P. Pine 30" dia. bears S15°55'E 34.8 feet  
 (record S18°E 33.0 feet)  
 Tamarack 12" dia. bears N21°02'W 29.2 feet  
 (B.L.M. N23°W 29.0 feet)

E 1/16 corner 2 : Set a 2" x 30" flanged G.I. pipe  
 11  
 with a 2-1/2" brass cap exposed 7" in a mound of stone  
 from which I mark the following trees as required,  
 taking measurements to the center of the tree at the  
 lower blaze in which I place a brass washer marked  
 LS 1679:

D. Fir 11" dia. bears N79°38'E 15.6 feet  
 D. Fir 13" dia. bears S39°25'W 32.5 feet

CE 1/16 corner Section 2.: Set a 2" x 30" flanged G.I.  
 pipe with a 2-1/2" brass cap exposed 10" from which  
 I mark the following trees as required, taking measure-  
 ments to the center of the tree at the lower blaze  
 in which I place a brass washer marked LS 1679:

D. Fir 13" dia. bears S70°00'E 20.5 feet  
 D. Fir 12" dia. bears N11°02'W 23.8 feet