

## Chans.

Thence returned to the corner common to secs. 16, 17, 20 and 21. This corner is plainly marked and is recognized by residents.

Thence due west on section line.

20.00 Established a 1/16 corner, a basalt rock 12 x 7 x 4, properly marked and bedded in rock.

40.80 Old original 1/4 common corner for secs. 17 and 20, plainly marked 1/4

Thence returned east on this line

20.40 Corrected the 1/16 corner last mentioned above.

Thence due north on 40 line

20.00 Est. a 1/16 corner for center of SE/4 sec. 17, a basalt rock 12 x 10 x 5 properly marked and bedded in stone.

Thence due west on 40 line.

20.40 Est. a 1/16 corner common to SW/4 and SE/4 sec. 17, a basalt rock 8 x 8 x 4 properly marked and bedded in stone.

40.40 Est. a 1/16 corner for center of SW/4 sec. 17, a basalt rock 12 x 6 x 4 properly marked and set in mound of rock.

Thence due south on 40 line.

20.00 East and west sec. line between secs. 17 and 20. Est. a 1/16 corner, a basalt rock 9 x 7 x 5 properly marked and bedded in stone.

The above survey was made on application of Jesse Jones.

*J. Lucas*  
Deputy County Surveyor