

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. F-20

History of original corner establishment:

None. Corner established this survey.

DIAGRAM  
T14S R27E  
NE 1/16  
•  
S11  
1993  
PLS 2405

Description of Corner Evidence Found:

None. Corner established this survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2-1/2"x30" aluminum pipe with 3-1/4" aluminum cap, stamped as shown in the DIAGRAM, 26" in the ground.

From Which:

White Fir, 16" dia., bears N60°05'E, 14.9 ft., scribed: NE 1/16 S11 BT  
White Fir, 12" dia., bears S34°54'W, 29.9 ft., scribed: NE 1/16 S11 BT

Measurements to BT's taken with an Electronic Tacheometer with bearings based on the survey control network. Set steel fence post with Land Survey Monument (54-9) and Property Boundary (54-2) signs 5' north of the monument. Nailed a brass washer stamped PLS 2405 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs.

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Susan E. Newstetter*

OREGON  
JULY 29, 1989  
SUSAN E. NEWSTETTER  
2405

Renewal Date: 12/31/94

This work was performed by:  
Susan E. Newstetter PLS 2405  
Witnessed by: Rick Saul, Brad  
Cates and D. Mitchell Ferguson  
July 27, 1993  
Refer to Grant Co. Survey No.: 1279

Office of Surveyors County of Grant  
State of OR I hereby certify that the within instrument was  
filed in this office for record on the 21 day of Jan, 19 94  
Robert D. Baggett by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)