


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

E-3

History of original corner establishment:

Original corner established in 1901 by George Campbell.  
Set stone 15x10x6 marked 1/4 on N face from which:  
A <sup>2 1/2"</sup> pine brs, S55°E 209 lks (137.9)



MOS 1115

Description of corner evidence found: Stone - Searched for not found, 40" pine stump with visible scribes brs, S55°E 137.9'

Description of monument and accessories I established to perpetuate the original location of this corner:

Cap marked

Set 2 1/2" x 30" aluminum pipe with 2 1/2" aluminum cap rising 6" in stone mound.  
New 137s:  
14" PP brs, N15 1/2°E 14.9'  
marked 1/4 56 BT  
12" PP brs, S65°E 55.3'  
marked 1/4 57 BT

7145 R35E

1/4 56  
4 57  
1988  
LS1020

I hereby certify the above corner was perpetuated as described in Dec. 1958.

REGISTERED PROFESSIONAL LAND SURVEYOR

*George W. Colvin, Jr.*

OREGON  
FEBRUARY 14, 1975  
GEORGE W. COLVIN, JR.  
1020

Office of County Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office for record on the 9 day of Nov, 1987  
Robert D. Bayth  
(COUNTY OFFICIAL) (DEPUTY)