


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original corner established by Samuel Lackland, deputy surveyor, under G.L.O. contract No. 357 dated July 2, 1880. Surveyor general's record states: North between Sections 5 and 6 Va. 18°45' East.

40.00 Set post for 1/4 section corner with pits and mound as per instructions.



C-5
F.B. 6 P. 10,11

Description of corner evidence found:

No evidence of corner found, considered lost and re-established by survey. Corner falls in grass-sage swale in scattered Pine timber. No evidence of post or pits and mound found. No fence lines or other evidence of occupation present.

Description of monument and accessories established to perpetuate the original location of this corner:

At proportionate position as determined by survey set a 2-1/2"O.D.x30" long aluminum pipe 26" in ground with a 2-1/2" diameter aluminum cap marked as shown: No stone available for mound.

Marked bearing trees:

A 19" Ponderosa Pine bears South 63° West, 60.8 ft., scribed "1/4S6BT"; a 17" Ponderosa Pine bears South 27-1/2° East, 114.6 ft., scribed "1/4S5BT". Painted a 6" red band and face blazes red. Nailed signs 54-9 and 54-3 to BT'S. Nailed a brass washer stamped "LS 1026" to face blazes of BT'S. Set a steel fence post 5 ft. North of cap with sign 54-9. Bearings are by staff compass and declination is 19-1/2° East.

I hereby certify that the above corner monument was re-established as herein described on October 11, 1989.

Witnesses: David B. Armstrong

See C.S. #1122 & #1123

REGISTERED
PROFESSIONAL
LAND SURVEYOR

David B. Armstrong

12/12/89 OREGON
AUGUST 22, 1975
DAVID B. ARMSTRONG
1026

Office of Surveyor County of Grant
State of Oregon, I hereby certify that the within instrument was filed in this office
for record on the 13 day of Feb, 1990
Robert D. Buggs by _____
(COUNTY OFFICIAL) (DEPUTY)