


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
Corner not previously established.



C-7  
F.B. 9 P. 37,38

Description of corner evidence found:

None. Corner not previously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position as determined by survey set a 2-1/2"O.D.x30" long aluminum pipe 26" in ground with a 2-1/2" diameter aluminum cap marked as shown: Raised a 3 ft. diameter stone mound to cap.

Marked bearing trees:

A 19" Ponderosa Pine bears North 68° East, 49.7 ft., scribed "C1/4S5BT"; a 17"x10" Double Ponderosa Pine bears North 14° West, 26.1 ft., scribed "C1/4S5BT". Painted a 6" red band and face blazes red. Nailed signs 54-9 and 54-3 to BT'S. Nailed a brass washer stamped "LS 1026" to face blazes of BT'S. Set a steel fence post 5 ft. North of cap with sign 54-9. Bearings are by staff compass and declination is 19-1/2° East.

I hereby certify that the above corner monument was established as herein described on November 9, 1989.

Witnesses: Wes G. Heigh  
Paul D. Woodworth

See C.S. #1123

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*David B. Armstrong*

12/22/89 OREGON  
AUGUST 22, 1975  
DAVID B. ARMSTRONG  
1026

Office of Surveyor County of Grant  
State of Oregon, I hereby certify that the within instrument was filed in this office  
for record on the 13 day of Feb, 1990  
Robert D. Boyer by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)