


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Original survey by Henry W. Cooke in 1884.  
Set: Basalt stone, 18X12X10, 12" in ground, marked 1/4 on W face.  
BT's: 36" pine, N80°W, 12 links=7.92'  
24" pine, S40°E, 20 links=13.2'



Description of corner evidence found:


No trace of either monument or bearing trees found, believe that road construction may have destroyed them.

Description of monument and accessories established to perpetuate the original location of this corner:

Set 2 1/2"X30" alum. pipe with cap 23" in ground in a stone mound. Corner falls in edge of road fill on West side. The following bearing trees were marked:  
20" p. pine, S85 1/2°W, 34.9' to face, marked: "1/4 S2 BT", 35.9' to CL.  
8" W. fir, S23°E, 82.0' to face, 82.4' to CL, marked: "1/4 S1 BT"  
Above trees have painted red faces and red bands, USFS signs, and a brass washer marked 1658 attached to the lower portion of face.  
Variation 18 E using staff compass.  
Witnessed by Randall Schulson Aug. 1983.

Alum. cap stamped as shown:

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR  
*Ronald H. Schulson*  
OREGON  
JULY 14, 1978  
RONALD H. SCHULSON  
1658



Office of *Surveyor* County of *Grant*  
State of *Oregon*, I hereby certify that the within instrument was filed in this office  
for record on the *30* day of *Nov*, 19*83*  
*Robert D. Sayre* by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)