


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established in 1881 by Forest W. Campbell under G.L.O. Contract No. 380. Surveyor General records state:

- Set Pine post from which:
 - 18" Tamarack bears N70E-30 lks.
 - 6" Pine bears S80W-30 lks.



Description of corner evidence found:

No evidence of the original corner or its accessories exist. Forest Service record of an Iron pin 40' North of a Fir tree on the East side of Hwy. 395 not accepted as a perpetuation of the corner for the following reasons. (1) Falls in the Southbound lane of Hwy #395 and could not have extended 18" above ground per Forest Service record. (2) Unable to find Iron pin 40ft. in any direction from cited Fir tree. (3) Iron pin not of record. (4) Corner per Forest Service record would fall approx. 80ft. East of Section line which is not consistent with other N/S bearings found in this Township.


Description of monument and accessories established to perpetuate the original location of this corner

Set 2 1/2" x 30" Gal. steel pipe with a 2 1/2" Brass cap 25" in the ground.

From which:

- 12" Pine bears N78 1/2 W-60.2 ft. scribed 1/4 S16 upper blaze and a lower blaze scribed BT and with a 1" Brass Disk stamped L.S. 896.
- 9" Pine bears N64 E-128.8 ft scribed 1/4 S15 upper blaze and a lower blaze scribed BT and with a 1" Brass Disk stamped L.S. 896.

Set steel guard post 4 ft. North with sign 54-4.
 Posted signs 54-4 and 54-3 on BT's.
 Painted red band around BT's and painted blazes red.



**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Larry D. Bishop

OREGON
JULY 11, 1969
LARRY D. BISHOP
896

Office of Surveyor County of Grant
 State of Oregon, I hereby certify that the within instrument was filed in this office
 for record on the 19 day of Feb 1981
Robert D. Begett by _____
 (COUNTY OFFICIAL) (DEPUTY)