


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
None



Description of corner evidence found:  
None

This corner was established as part of a subdivisional section breakdown survey.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 26 in. in the ground with a mound of earth to the cap, from which:

- A 6½ in. dia. Pine bears N86°W - 139.1 ft., scribed: E1/16 S14 BT
- A 7 in. dia. Pine bears S74°W - 151.6 ft., scribed: E1/16 S23 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-9 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set steel fence posts (A) North of the monument with 54-2 and 54-9 signs attached, and (B) South of the monuments with a 54-2 sign attached.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.


This corner was monumented on September 8, 1983.

Witnessed by: Robert D. English  
Aaron C. Hoeft

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*  
OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

Cap marked:



Office of..... County Surveyor..... County of..... Grant.....  
State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the 15 day of Sept....., 1983  
*Robert D. English* by.....  
(COUNTY OFFICIAL) (DEPUTY)