


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None



Description of corner evidence found:

None

This corner was established as part of a subdivisional section breakdown survey to determine property boundaries of U. S. Forest Service and privately owned parcels.

Description of monument and accessories | established to perpetuate the original location of this corner:

Set: A 2½ in. by 30 in. aluminum pipe, with a 2½ in. aluminum cap, 27 in. in the ground with a mound of earth to the cap, from which:

A 12½ in. dia. L. P. Pine bears S48½°E - 263.0 ft.,  
scribed: NE 1/16 S23 BT

A 8 in. dia. Lodgepole Pine bears S63½°W - 232.0 ft.,  
scribed: NE 1/16 S23 BT

Each new bearing tree has a brass washer stamped PLS 1106 nailed to the face of the blaze, and has 54-3 and 54-4 signs attached. Painted the face of the blaze and a 6 in. band around each bearing tree red.

Set steel fence posts (A) East of the monument with 54-2 and 54-9 signs attached, and (B) North of the monument with a 54-2 sign attached.

Used a steel tape and a magnetic staff compass, with 20° East declination. Measured to the center of the bearing trees.

This corner was monumented on September 8, 1983.


Witnessed by: Robert D. English  
Aaron C. Hoeft

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106

Cap marked:



Office of.....County Surveyor..... County of..... Grant.....  
State of..... Oregon....., I hereby certify that the within instrument was filed in this office  
for record on the 15 day of Oct, 1983  
*Robert D. English* by.....  
(COUNTY OFFICIAL) (DEPUTY)