


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

Index No. S-22



No record of subsequent remonumentation found in County Records .

Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 30 inches in the ground.

Set steel fence posts South and West of the corner and attached signs 54-2 and 54-9.

Established 2 new BT's:

A 12" Pine bears N14°E 91.7 feet scribed NW 1/16 S25 BT

A 18" Fir bears S29°E 99.6 feet scribed NW 1/16 S25 BT

New BT's have a lower blaze scribed BT with brass washer stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 to all BT's and painted a red around the trees above the upper blaze.

The corner is located 55.5 ft South and 28.2 ft west of a fence corner. The fences go West & South from the corner.

Used steel tape and magnetic compass with 19½° east declination. Measured to center of Bts.

See map of survey


This corner set November 11, 1979

Witnesses: D. Kaufman, PLS  
B. English

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106



Office of County Surveyor County of Grant  
Oregon  
State of Oregon, I hereby certify that the within Instrument was filed in this office  
for record on the 9 day of Jan 1980  
Robert D. Basist by \_\_\_\_\_  
(COUNTY OFFICIAL) (DEPUTY)