


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

Index No. T-22



No record of subsequent remonumentation found in County Records .

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 20 inches in the ground and surrounded with a mound of stones to the cap .

Set steel fence posts North and East of the corner and attached signs 54-2 and 54-9.

Established 2 new BT's:

A 11 1/2" Pine bears N57°E 14.1 feet scribed CW 1/16 S25 BT

A 15" Pine bears S20°W 51.6 feet scribed CW 1/16 S25 BT

New BT's have a lower blaze scribed BT with brass washer stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 to all BT's and painted a red ring around the trees above the upper blaze.

Used steel tape and magnetic compass with 19 1/2° east declination . Measured to center of Bts.


See map of survey

This corner set November 6, 1979

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106



- Witnesses: D. Kaufman, PLS
B. English
D. Bartleson
C. Kelly

Office of County Surveyor County of Grant
State of Oregon , I hereby certify that the within instrument was filed in this office
for record on the 7 day of Jan 1980
Robert D. Smith by _____
(COUNTY OFFICIAL) (DEPUTY)