


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None

Index No. R-4



No record of subsequent remonumentation found in County Records .

Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 24 inches in the ground and surrounded with a mound of stones to the cap.

Set steel fence posts North and West of the corner and attached signs 54-2 and 54-9

Established 2 new BT's:

A 14" Fir bears N13°W 49.6 feet scribed E 1/16 S19 BT

A 17½" Fir bears S15°W 65.2 feet scribed E 1/16 S30 BT

New BT's have a lower blaze scribed BT with brass washer stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 to all BT's and painted red ring around the trees above the upper blaze.

Used steel tape and magnetic compass with 19½° east declination. Measured to center of Bts.

See map of survey


This corner set November 5, 1979

Witnesses: D. Kaufman, PLS
B. English

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William R. Wells

OREGON
JULY 22, 1977
WILLIAM R. WELLS
1106



Office of County Surveyor County of Grant
 State of Oregon, I hereby certify that the within Instrument was filed in this office
 for record on the 9 day of Jan 1980
Robert D. English by _____
 (COUNTY OFFICIAL) (DEPUTY)