


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:  
None

Index No. T-3



No record of subsequent remonumentation found in County Records.

Description of corner evidence found:

None

Description of monument and accessories established to perpetuate the original location of this corner:

At the corner position a 2 inch by 30 inch iron pipe, with brass cap marked as shown, was set 27 inches in the ground and surrounded with a mound of earth to the cap.

Set a steel fence post North of corner and attached signs 54-2 and 54-9.

Established 2 new BT's:

A 9" Red Fir bears S51 1/2°W 7.7 feet scribed C 1/4 S30 BT

A 8 1/2" Red Fir bears N84°W 31.8 feet scribed C 1/4 S30 BT

New BT's have a lower blaze scribed BT with brass washer stamped PLS 1106 nailed flush.

Attached signs 54-3 and 54-4 to all BT's and painted a red ring around the trees above the upper blaze.

Used steel tape and magnetic compass with 19 1/2° east declination. Measured to center of BT's. See map of survey.


This corner set October 23, 1979

Witnesses: D. Kaufman, PLS  
B. English  
C. Kelly  
D. Bartleson

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*William R. Wells*

OREGON  
JULY 22, 1977  
WILLIAM R. WELLS  
1106



Office of... County Surveyor..... County of... Grant  
State of... Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the... 9... day of... Jan... 19 80  
*Robert D. Shyatt* by.....  
(COUNTY OFFICIAL) (DEPUTY)